


Off temp: 35°F +/- 5° On temp: 4°F higher

2A @ 24VAC



Installation:

Drill a 1/2" hole in duct on the cold air side of damper.

Fasten sensor with 2 self tapping screws provided.

Wire according to diagram.





