

SIGNATURE HARDWARE  
OVERHANG/REVEAL CHANGE IS  
NOT RECOMMENDED FOR THIS SINK

OUTSIDE OF SINK

UNDERMOUNT

INSIDE OF SINK

DROP IN

