
TEMP-GARD™

MODEL - Z7000-VB
VACUUM BREAKER

⚠ **WARNING**: Cancer and Reproductive Harm - www.P65Warnings.ca.gov
⚠ **ADVERTENCIA:** Cáncer y daño reproductivo - www.P65Warnings.ca.gov
⚠ **AVERTISSEMENT:** Cancer et effets néfastes sur la reproduction - www.P65Warnings.ca.gov

INSTALLATION INSTRUCTIONS

1. SCREW FEMALE THREADS ONTO ELBOW OR SHOWERARM OF WATER SUPPLY.
2. ATTACH HOSE FROM HANDWALL UNIT TO MALE THREAD ON VACUUM BREAKER. ARROW ON VACUUM BREAKER SHOULD POINT IN DIRECTION OF WATER FLOW.



Maintenance and Trouble Shooting Guide		
Problem	**Cause**	**Solution**
Vacuum breaker or shower valve makes loud noise.	Large pressure difference causing piston in valve to move rapidly.	Alter water system such that pressure differential is no more than 5 psi from hot to cold.
Insufficient water flow	Handwall unit/ vacuum breaker combination restricting water flow.	Remove flow control device in handwall unit per local codes.
	Showerhead plugged.	Clean showerhead.
	Low Pressure.	Increase pressure.

ZURN INDUSTRIES, LLC 5900 Elwin Buchanan Drive, Sanford, NC U.S.A. 27330, Ph. 1-800-997-3876, Fax 919-775-3541
In Canada: **ZURN INDUSTRIES LIMITED** 7900 Goreway Drive, Unit 10, Brampton, Ontario L6T 5W6, Ph. 905-405-8272, Fax 905-405-1292

Rev. B Date: 10/19/2018 C.N. No. SAN008373 Prod. | Dwg. No. CF1118