

Fire Hydrant Parts

Interchangeable/Identical - 4-1/2" Valve Opening

▼ Except Super Centurion 350

Description	4-1/2" Centurion Fire Hydrant	4-1/2" Improved Fire Hydrant	4-1/2" Modern Improved Fire Hydrant	4" Mueller 107 FireHydrant
Operating nut	A-1 Same as H-51	H-51	Same as H-51	Not the Same
Weather cap	A-2* Interchangeable with H-52	H-52 Interchangeable with A-2	Not the Same	Not the Same
Hold down nut o-ring	A-3 Same as H-101	H-101	H-101	Not the Same
Pipe plug	A-7 Same as H-98	H-98	H-98	Not the Same
Stem o-ring	A-12 Same as H-93	H-93	H-93	Not the Same
Hose nozzle cap	A-21 Same as H-205	H-71**	H-205	H-71**
Hose nozzle cap gasket	A-19 Same as H-72	H-72	H-72	H-72
Pumper nozzle cap	A-17 Same as H-207 in 4 1/2" Size Only	H-67***	H-207	H-67***
Pumper nozzle cap gasket	A-15 Same as H-68	H-68	H-68	H-68
Chain	A-22 Same as H-69	H-69	H-69	H-69
Safety flange bolt and nut	A-26 ▼ Same as H-78	H-78	Not the Same	H-78
Safety flange	A-28 ▼ Same as H-77	H-77	Not the Same	H-77
Safety flange gasket	A-27 Same as H-76	H-76	Not the Same	H-76
Safety stem coupling	A-25 Same as H-125	H-125	H-125	H-125
Clevis pin	A-30 Same as H-136	H-136	H-136	H-136
Cotter pin	A-29 Same as H-137	H-137	H-137	H-137
Main valve	Not the Same ▼	H-88	H-88	Not the Same
Lower valve plate	A-46 Same as H-89	H-89	H-89	Not the Same
Safety flange repair kit	A-300 ▼	A-300	Not the Same	A-24150 Same as A-300 LESS LUBRICANT OIL
Barrel extension sections	A-319 ▼	Not the Same	4 1/2" A-333 Same as A-319	A-24155 Same as A-319 LESS LUBRICANT OIL

* These parts are not the same but can be interchanged with H-52

** These parts are not the same but can be interchanged with A-21 or H-205.

*** These parts are not the same but can be interchanged with A17 or H-207.