


| ITEM | DESCRIPTION | PART NO. |
|------|-----------------------------------|------------|
| 1 | STRAINER ASSEMBLY | 6462 |
| 2 | BACK PANEL | BP3 |
| 3 | BUBBLER HEAD | 5703M |
| 4 | BUTTON, PUSH, FLANGED, ASSY | PBA6 |
| 5 | BUTTON, PUSH, FLANGED, WITH VALVE | 5874PBF |
| 6 | BOTTOM PLATE | PBM1109 |
| ** | MOUNTING FRAME | MTGFR.SM |
| 8 | CHILLER | HCR8 |
| 9 | SPANNER WRENCH | 0006983506 |
| 10 | TRAP | 0005982900 |
| 11 | DRIVER, NOZZLE .25 HEX (OPTIONAL) | 0002082253 |
| 12 | VALVE REPAIR KIT | VRK5874 |

NOTES:

- 1 5874PBF (ITEM 5) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 12) AND PBA6 FLANGED PUSH BUTTON (ITEM 4).
- 2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.

** REQUIRED - SOLD SEPARATELY



PARTS BREAKDOWN

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

| | | | |
|---|------------------------------|---|---|
|  | | 1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM WEBSITE: WWW.HAWSCO.COM | |
| | | ECN NO. REVISED PER BY ECN: 5527 FV | MODEL(S) H1109.8 |
| DRAWN DATE CHKD F. VASQUEZ 08-25-08 DP | APPROVED DATE FV 04/02/20 | REVISION 19 | SCALE: 1:5 DRAWING TYPE: PARTS BREAKDOWN SIZE: A SHEET 1 OF 1 |