

Rev. 4-17 Shaded area indicates changes

Mueller B-101 Repair Kit – 681844 (See page 1.9 for Item No.)

Item Number	Part No.	Description
4	580610	1 - Friction Collar
5	48130	1 - Retaining Pin
57	88366	1 - Cutting Grease
19	500887	1 - Wiper Ring
11	500687	1 - Cap Packing
21	500692	1 - Bearing
32	40066	1 - Small Saddle Gasket
33	40067	1 - Large Saddle Gasket
27	500670	1 - Valve Body O-ring
28	682087	1 - By-Pass Valve Repair Kit
40	500673	1 - Gate Washer
56	500694	1 - Tool Retaining Screw
9	79269	2 - Boring Bar O-ring
51	41301	1 - Valve Stem O-ring

Mueller B-101 Bypass Repair Kit – 682087

Item Number	Part No.	Description
29	501373	2 - Screws
28/30	682053	1 - Bypass valve assembly with gasket
-	311815	1 - Nameplate
-	Form - 12084	1 - Instruction sheet