

HCC Holdings, Inc.

4700 West 160th
Cleveland, Ohio 44135

Phone: 800-321-9532
Website: www.Oatey.com



MEGABUBBLE® Leak Detector

Date: August 2017

High viscosity formula produces large, easily detected high strength blue bubbles with excellent cling properties for easier detection of gas leaks on pipes, fittings, tanks, coils, cylinders, pressure vessels, valves, etc. Longer lasting bubbles remain on surface allowing extra time for detecting even the smallest and slowest of gas leaks. Will not harm or stain metal, rubber or plastic surfaces. Non-toxic, non-corrosive formula can be used in lines carrying air, oxygen, nitrogen, natural or propane gas, carbon dioxide, refrigerants, and most other gases. Useful temperature range from -50°F to +200°F. For most convenient application use Product 45802 32 oz. spray applicator bottle or 45804 16 oz. spray applicator bottle.



APPROVALS & LISTINGS

MIL-L-25567D

SPECIFIC USES

Megabubble may be used to detect leaks on pipelines, fitting, tanks, coils, cylinders, pressure vessels, valves, and other hard surfaces.

SPECIFIC APPLICATIONS*

Megabubble may be used to detect leaks of gas, air, compressed air, nitrogen, natural gas, refrigerants, CO₂, and almost all other known gases.

*For special applications which may not be covered on this or other Oatey literature, please contact Oatey Technical Services Department by phone 1-800-321-9532, or fax 1-800-321-9535, or visit our technical database web-site at www.Oatey.com.

PHYSICAL PROPERTIES

Working temperature range: -50° to +200°F
 Appearance/color/odor: Blue liquid, odorless

DIRECTIONS FOR USE

1. Apply **Megabubble** directly to pipe joint, solder joint, valve stem or any other part being checked.
2. Visually inspect all joints, fittings, gaskets, flanges, seams and corroded surfaces which may have perforation. **Megabubble** indicates where leaks are located. Very small leaks may need a minute or longer to produce a detectable bubble cluster.
3. Repeat if desired - leak detection depends on careful inspection. Surfaces can be re-wetted and rechecked.
4. Do not dilute this product. Use directly from container.
5. If using dauber, keep free of dirt and foreign matter. If using spray and nozzle becomes clogged, remove and rinse with warm water.
6. Remove excess **Megabubble** residue with water spray or wipe off with damp rag.

WARNINGS OR CAUTIONS

- Read all cautions and directions carefully before using product.
- **KEEP OUT OF REACH OF CHILDREN.**

MATERIAL SAFETY INFORMATION

FOR MORE INFORMATION ON THIS PRODUCT, REQUEST SAFETY DATA SHEET (SDS) #7322E

For Delivery By Fax	Call 1-800-321-9535
Internet	See SDS section of www.Oatey.com

HMIS® ratings Health: 0
 Flammability: 0
 Physical hazard: 0

SIZE & PACKING

STOCK NUMBER	SIZE	PACKING	WEIGHT/CASE
45801	8 oz. dauber bottle	24	14.8 lbs.
45802	32 oz. spray bottle	12	30.0 lbs.
45803	1 gal. refill	4	38.0 lbs.
45804	16 oz. spray bottle	12	16.5 lbs.