




# SUBMITTAL DATA

## STARTING COLLAR —

**RX10 (no crimp)  
RX11 (crimp)**



RX10 Start Collar  
no crimp



RX11 Start Collar  
w/crimp



Start Collar w/  
Solid Ring

A	B	C	D	GA
<b>4</b>	3.5	1.75	1.0	30, 28
<b>5</b>	3.5	1.75	1.0	30, 28
<b>6</b>	3.5	1.75	1.0	30, 28
<b>7</b>	3.5	1.75	1.0	30, 28
<b>8</b>	3.5	1.75	1.0	30, 28
<b>9</b>	3.5	1.75	1.0	30, 28
<b>10</b>	3.5	1.75	1.0	30, 28, 26
<b>12</b>	3.5	1.75	1.0	28, 26
<b>14</b>	3.5	1.75	1.0	28, 26
<b>16</b>	3.5	1.75	1.0	28, 26
<b>18</b>	3.5	1.75	1.0	28, 26
<b>20</b>	3.5	1.75	1.0	26
<b>22</b>	3.5	1.75	1.0	26
<b>24</b>	3.5	1.75	1.0	26
<b>26</b>	3.5	1.75	1.0	26, 24
<b>28</b>	3.5	1.75	1.0	26, 24
<b>30</b>	3.5	1.75	1.0	26, 24
<b>32</b>	3.5	1.75	1.0	26, 24
<b>34</b>	3.5	1.75	1.0	26, 24
<b>36</b>	3.5	1.75	1.0	26, 24

Galvanized Steel, G30/40 coating standard, G90 available. Different GA avail.

Metals tabs with 1/4" bead for sheet metal application.

### PART NUMBER DESIGNATIONS

**RX10xx (no crimp)**

**RX11xx (with crimp)**

XX = Diameter (03-40)

Options:

RG = Solid Ring Collar

ex: RX1006RG 6" Solid Ring Start Collar

PROJECT: \_\_\_\_\_ COMPANY: \_\_\_\_\_ DATE : \_\_\_\_\_

LOCATION: \_\_\_\_\_ SUBMITTED BY: \_\_\_\_\_