




### P122 Spigot Adapter, Cast Iron


H x H



| Part Number | Size | N    |
|-------------|------|------|
| P122-040    | 4    | 9/16 |

### P123 Hub Adapter, Cast Iron

H x S




| Part Number | Size | N       |
|-------------|------|---------|
| P123-020    | 2    | 3- 7/8  |
| P123-030    | 3    | 4- 1/8  |
| P123-040    | 4    | 4-11/32 |

### P123R Hub Adapter, Cast Iron, Increaser

H x S

Plain End: Joint can be made with compression gasket or plastic lead & seal rope - Do Not use hot lead



| Part Number | Size    | N       |
|-------------|---------|---------|
| P123R-213   | 1-1/2X2 | 3- 9/16 |
| P123R-342   | 3X4     | 4       |

### P130 Repair Coupling


H x H



| Part Number | Size  | L        |
|-------------|-------|----------|
| P130-015    | 1-1/2 | 1- 1/2   |
| P130-020    | 2     | 1-11/16  |
| P130-030    | 3     | 3- 3/16  |
| P130-040    | 4     | 3- 3/4   |
| P130-060    | 6     | 6-3/8    |
| P130-080    | 8     | 8- 5/16  |
| P130-100    | 10    | 10- 7/16 |

### P300 1/4 Bend

H x H



| Part Number | Size  | G        |
|-------------|-------|----------|
| P300-015    | 1-1/2 | 1-3/4    |
| P300-020    | 2     | 2- 5/16  |
| P300-030    | 3     | 3- 1/16  |
| P300-040    | 4     | 3-7/8    |
| P300-060    | 6     | 5        |
| P300-080    | 8     | 6        |
| P300-100    | 10    | 9- 13/16 |
| P300-120    | 12    | 10- 3/4  |