

Operation & Maintenance

Temperature Control

1) Turn shower handle counterclockwise approximately 1/4 turn to put valve in cold position.



2) Turn shower handle counterclockwise approximately 1/2 turn to put valve in warm position.



3) Turn shower handle counterclockwise approximately 3/4 turn to put valve in hot position.



Troubleshooting Chart		
Finish is spotting.	Elements in water supply may cause water staining on finish.	Clean finished trim area with a soft cloth using mild soap and water or a non-abrasive cleaner and then quickly rinse with water.