



Position corner caddy on wall at desired location and mark hole locations with nail or punch. Mount holder with 4 - $\#8 \times 1-1/4"$ round head zinc plated steel screws provided.

