

SERVICE PARTS LIST

BULLETIN NO. 54-07-2435

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS


REVISED BULLETIN

DATE May 2015

3 in 1 JACKET: Jacket with M12™ Heated Hoodie

Bare Tool: 2170S, 2170M, 2170L, 2170XL, 21702X, 21703X

Kit: 2171S, 2171M, 2171L, 2171XL, 21712X, 21713X



M12™ Heated 3 in 1 Jacket Only-


2170S	M12™ Heated 3 in 1 Jacket - Small
2170M	M12™ Heated 3 in 1 Jacket - Medium
2170L	M12™ Heated 3 in 1 Jacket - Large
2170XL	M12™ Heated 3 in 1 Jacket - Extra Large
21702X	M12™ Heated 3 in 1 Jacket - Extra Large (2X)
21703X	M12™ Heated 3 in 1 Jacket - Extra Large (3X)

M12™ Heated 3 in 1 Jacket Kit-

2171S	M12™ Heated 3 in 1 Jacket - Small
2171M	M12™ Heated 3 in 1 Jacket - Medium
2171L	M12™ Heated 3 in 1 Jacket - Large
2171XL	M12™ Heated 3 in 1 Jacket - Extra Large
21712X	M12™ Heated 3 in 1 Jacket - Extra Large (2X)
21713X	M12 [™] Heated 3 in 1 Jacket - Extra Large (3X)

NOTE:

Both the Compact M12 battery pack and XC M12 battery pack can be used in the two battery holders. Both battery holders are interchangeable with all jackets, hoodies and vests. Kit versions of the 3 in 1 jackets come with the 43-72-1025 battery holder.



43-72-1000 Battery Holder

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	43-72-1000	Battery Holder	(1)
2	12-20-2330	Service Nameplate - Battery Holder	· (1)
3	10-20-2318	Warning Label - Battery Holder	(1)

43-72-1025 Battery Holder

	FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
	1	43-72-1025	Battery Holder	(1)
	2	12-20-1025	Service Nameplate - Battery Holder	(1)
	3	10-20-1028	Warning Label - Battery Holder	(1)

FIG.

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.