

DEALER SERVICE BULLETIN

Number: DSB 12-0007

Date: 2/22/12

Supersedes: New

Title: Single Stage Pressure Switch
HK06ZB104

PRODUCT CATEGORY:

Residential Furnaces

EXPIRED

MODELS AFFECTED:

Bryant	Carrier	Payne
340AAV	58MCB	PG9MAB
350AAV	58MXB	
353AAV	58MEB	

Beginning Serial Number(s): 0110A

Ending Serial Number(s): 5210A

SITUATION:

We are experiencing higher than expected failure of the HK06ZB104 single stage differential pressure switch (shown in figure 1) used in the above listed condensing gas furnace models built in 2010. This switch is not used on mid-efficiency furnaces.



This Policy will terminate on Decemeber 31, 2013

Warning: Do not perform any of the servicing instructions provided in this Service Bulletin unless you are a trained and qualified technician. Observe all precautions in the instructions, equipment tags, labels, and observe all other safety precautions that may apply. Failure to follow this warning could result in property damage, personal injury or death.

Field Action:

On a complaint basis only, replace a failed HK06ZB104 differential pressure switch with an HK06NB123 or HK06NB124 switch for furnaces within the affected serial number range. The HK06NB124 switch is the HK06NB123 switch with an additional removable metal mounting bracket. These switches can be obtained from your distributor.

Parts/Kits:

The current service replacement switch will not change for these models. Service replacement switches will use the current part number HK06NB123 as a replacement for the HK06ZB104 switch. The switches are exact fits and are interchangeable between each other.

**EXPIRED**