

SLW-3512-1.5, SLW-3510-1.5

Two Handle Widespread Lavatory Faucet

Installation Brief





■ Need Help?

Contact Symmons customer service at Phone: (800) 796-6667 Email: gethelp@symmons.com

Monday - Friday 7:30 am - 6:00 pm EST


Please check Symmons website for technical help, the latest product information and warranty policy. www.symmons.com/service

Model Number

☐ SLW-3512-1.5 Two Handle Widespread Lavatory Faucet with Lift Rod and Metal Drain Assembly


☐ SLW-3510-1.5
Two Handle Widespread Lavatory
Faucet without Lift Rod Hole and
Metal Drain Assembly





Dimensions Dia Two Handle Widespread Lavatory Faucet 6-3/8" 8"(203 mm) min !-(162 mm) 16"(406 mm) max **←** 5/8" (16 mm) 7-1/4" 4" (102 mm) min 2-1/2" dia (185 mm) 1-7/8" (64 mm) 2-3/8" (60 mm) -(48 mm) 3-7/8" 6" (152 mm) 2-1/2" (98 mm) Deck thickness -2" dia (64 mm) 1-3/8" (35 mm) max 7/7 (51 mm) Hole size - 1" dia 5/8" dia 1-1/2" (38 mm) min (25 mm) Hole size (16 mm) 1-5/8" (41 mm) max 1-1/8" (29 mm) min 1-1/2" (38 mm) max Flexible hose ·5/8" (16 mm) 1/2"-14 NPSM Note: Dimensions subject to change without notice.

Parts Assembly Dia Two Handle Widespread Lavatory Faucet



Replacement Parts	
Part Number	Item
RL-058*	handle assembly handle screw collar escutcheon gasket
LN-333-KIT FLR-102-1.5-KIT FLR-102-0.5	aerator & removal tool flow rates 2.2 gpm (8.3L /min) 1.5 gpm (5.7L /min) 0.5 gpm (1.9L /min)
KN-114 (hot) OFF = CW KN-113 (cold) OFF = CCW	valve cartridge KN-113 identified by groove
LN-341*	Lift rod

Ordering replacement parts:

Call Symmons customer service at (800) 796-6667 Monday-Friday, 7:30 am - 6:00 pm EST or check our website at www.symmons.com for a list of Symmons distributors.

Note: When ordering replacement parts for faucets with an optional decorative finish, append appropriate three letter finish suffix code to part numbers marked with an asterisk ().

WARNING: This product can expose you to chemicals including lead, which is known to the state of California to cause cancer, birth defects, or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.