



SERVICE PARTS LIST

BULLETIN NO.
54-06-2110

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
USB RECHARGEABLE HARD HAT HEADLAMP				Feb. 2019
CATALOG NO.	2111-21	STARTING SERIAL NO.	J26A	
WIRING INSTRUCTION				

EXAMPLE:

00	0
----	---

 Component Parts (Small #)
 Are Included When Ordering
 The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	31-15-0605	Rubber USB Cover	(1)
2	42-36-0215	Strap Bracket	(1)
3	45-56-0085	Strap	(1)
4	42-70-2103	Hard Hat Clips (Set of 4)	(1)
5	48-59-1202	Wall Plug and Micro-USB Cable (Optional)	(1)
6	48-11-2130	REDLITHIUM® USB Battery (Optional)	(1)
7	12-20-2104	Service Nameplate (Not Shown)	(1)

FIG. NOTES
 7 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.