

Fire Hydrant Repair Kits

4", 4-1/2", 4-1/4" Main Valve Opening

Hydrant Style	Bonnet Repair Kit	Safety Flange Repair Kit	Extension Kit	Shoe Repair Kit	Main Valve Repair Kit	Tamper Proof Retrofit Kit*	
						Left	Right
Super Centurion®350	-	A-300-35	A-319-35	-	-	284275	282476
Super Centurion 250 & 200	280355	A-300	A-319	280356	280358	284275	282476
Centurion®	280355	A-300	A-319	280356	280358	284275	284276
Improved	280360	A-300 (after 1972)	A-319-11 (after 1972)	280362 (4-1/4")	280365 (4-1/4")	284275	284276
		A-300-00 (prior to 1972)	A-319-00 (prior to 1972)	280363 (4-1/2")	280366 (4-1/2")		
Modern Improved	-	A-307	A-319-11	280391	280393	-	-
Mueller® 107	280368 (4")	A-300 (4")	A-319 (4")	280370 (4")	280372 (4")	-	-
Standard Post (A-413)	-	-	A-322 (4-1/4" and 4-1/2")	-	-	-	-
Standard Traffic (A-414)	-	A-306	A-337	-	-	-	-

5" and 5-1/4" Main Valve Opening

Hydrant Style	Bonnet Repair Kit	Safety Flange Repair Kit	Extension Kit	Shoe Repair Kit	Main Valve Repair Kit	Tamper Proof Retrofit Kit*	
						Left	Right
Super Centurion 350	-	A-301-35	A-320-35	-	-	284275	282476
Super Centurion 250 & 200	280355	A-301	A-320	280357	280359	284275	282476
Centurion	280355	A-301	A-320	280357	280359	284275	284276
Super Centurion Spin-In	280355	A-301	A-320	-	-	-	-
Centurion Spin-In	280355	A-301	A-320	-	-	-	-
Improved	280361	A-301 (after 1972)	A-320 (after 1972)	280364	280367	284275	284276
		A-301-00 (prior to 1972)	A-320-00 (prior to 1972)				
Modern Improved	-	-	A-320	280392	280394	-	-
Mueller 107	280369 (5")	A-301 (5")	A-320 (5")	280371 (5")	280373 (5")	-	-
Standard Post (A-413)	-	-	-	-	-	-	-
Standard Traffic (A-414)	-	A-308	-	-	-	-	-

* The A-374 Wrench (To operate Tamperproof Hydrant), A-384 Spanner Wrench (To assemble and disassemble Tamperproof Operating Nut Cap) and A-391 Wrench (To assemble and disassemble Tamperproof Cast Iron Hold Down Nut) are also required.