

## McGuire Manufacturing Co., Inc.

60 Grandview Court P.O. Box 746 • Cheshire, CT 06410 203-699-1801 • Fax: 203-699-1813


www.mcguiremfg.com

## Part No.

8089 and 8090 Series

**Boston Sweat P-Trap** 

## **PRODUCT SPECIFICATION**



ROUGHING MEASUREMENTS							
NO.	TRAP DIMENSIONS						_
	INLET	OUTLET	A	В	С	D	E
8090CBOS4	1-1/4"	1-1/2" w/4" Sweat Extension	8"	5"	3"	4-1/2"	5"
8090CBOS6	1-1/4"	1-1/2" w/6" Sweat Extension	10"	7"	3"	4-1/2"	5"
8090CBOS8	1-1/4"	1-1/2" w/8" Sweat Extension	12"	9"	3"	4-1/2"	5"
8090CBOS12	1-1/4"	1-1/2" w/12" Sweat Extension	16"	13"	3"	4-1/2"	5"
8089CBOS4	1-1/2"	1-1/2" w/4" Sweat Extension	8"	5"	3"	4-1/2"	5"
8089CBOS6	1-1/2"	1-1/2" w/6" Sweat Extension	10"	7"	3"	4-1/2"	5"
8089CBOS8	1-1/2"	1-1/2" w/8" Sweat Extension	12"	9"	3"	4-1/2"	5"
8089CBOS12	1-1/2"	1-1/2" w/12" Sweat Extension	16"	13"	3"	4-1/2"	5"

Note: Minimum seal 2"

(1) o

See options and accessories section for details on product variations.

ASME A112.18.1-2011/CSA B125.2-11

## **Specifications:**

P-Trap shall be chrome plated cast brass body with cleanout, 17 gauge seamless tubular sweat extension, cast brass ground joint elbow, and cast brass slip nuts. **No reducing washers.** With (shallow, deep, bell) (steel, brass) or (forged brass with set screw) flange.