

PRODUCT SPECIFICATIONS

Service/Utility Wall Mount Faucet. Faucet has a flow rate of 4.0 GPM, and is made of Chrome Plated Brass material, with a Quarter Turn Ceramic Disc valve. Faucet requires 2 faucet holes.

Mounting Type:	Wall Mount	
Special Features:	Solid Brass Construction 1/2" adjustable inlets with integral stops	
Finish:	Chrome	
Handle Type:	2" Lever Handle	
Hole Drillings:	2	
Material:	Chrome Plated Brass	
Valve Type:	Quarter Turn Ceramic Disc	
Valve Connection:	1/2" NPT Female	
Flow Rate:	4.0 GPM	
Spout Type:	Flexible Spout	



AMERICAN PRIDE. A LIFETIME TRADITION. Like your family, the Elkay family has values and traditions that endure. For almost a century, Elkay has been a family-owned and operated company, providing thousands of jobs that support our

families and communities.




Product Compliance: ADA

ASME A112.18.1/CSA B125.1

NSF 372 (lead free)

NSF 61


Clean and Care Manual (PDF)
Installation Instructions (PDF)
Limited Warranty (PDF)



In keeping with our policy of continuing product improvement, Elkay reserves the right to change product specifications without notice. Please visit elkay.com for the most current version of Elkay product specification sheets. This specification describes an Elkay product with design, quality, and functional benefits to the user. When making a comparison of other producers' offerings, be certain these features are not overlooked.



ITEM	IND. PART	DESCRIPTION
1	A55407	Spout
2	45918C	Handle, 2"
3	45923C	Right Cold Cartridge
4	45924C	Left Hot Cartridge
5	A55413	2" Adjustable Inlet
6	45912C	Body
7	98555C	V.B. Repair Kit



In keeping with our policy of continuing product improvement, Elkay reserves the right to change product specifications without notice. Please visit elkay.com for the most current version of Elkay product specification sheets. This specification describes an Elkay product with design, quality, and functional benefits to the user. When making a comparison of other producers' offerings, be certain these features are not overlooked.