



**Viega PEX Press Coupling**  
**Smart Connect feature, Zero Lead**  
 - PPSU  
 - Press connection  
**Model V5615**

P1	P2	Wt [lb]	Quantity	Part No	DG
3/8	3/8	0.022	25	49402	6
1/2	3/8	0.002	25	49342	6
1/2	1/2	0.027	25	49403	6
3/4	1/2	0.034	25	49343	6
3/4	3/4	0.040	25	49404	6
3/4	1 1/4	0.505	5	49347	6
3/4	1 1/2	0.118	5	49348	6
1	3/4	0.055	10	49354	6
1	1	0.068	10	49405	6
1	1 1/4	0.112	5	49357	6
1	1 1/2	0.151	5	49358	6
1 1/4	1 1/4	0.151	5	49407	6
1 1/4	1 1/2	0.165	5	49378	6
1 1/2	1 1/2	0.034	5	49408	6
2	1 1/2		5	49398	6
2	2		5	49409	6



**Viega PEX Press Test plug**  
**Zero Lead**  
 - Bronze  
 - Press connection  
**Model 2856ZL**

P	Wt [lb]	Quantity	Part No	DG
3/8	0.022	10	95000	6
1/2	0.035	10	95121	6
3/4	0.057	10	95141	6
1	0.108	10	95161	6



**Viega PEX Press Test plug**  
**Smart Connect feature, Zero Lead**  
 - PPSU  
 - Press connection  
**Model V5656**

P	Wt [lb]	Quantity	Part No	DG
3/8	0.002	25	49722	6
1/2	0.015	25	49723	6
3/4	0.021	25	49744	6
1	0.036	10	49765	6

**Valves**



**NEW**

**Viega PEX Press Stop valve**  
**Straight**  
**Zero Lead**  
 - Chrome-plated brass  
 - Press connection, compression  
 - 1/4 turn  
**Model 2842.3ZL**

P	CTS	Wt [lb]	Quantity	Part No	DG
3/8	1/4		10	94023	6
1/2	1/4		10	94031	6



**NEW**

**Viega PEX Press Stop valve**  
**Angled**  
**Zero Lead**  
 - Chrome-plated brass  
 - Press connection, compression  
 - 1/4 turn  
**Model 2842.4ZL**

P	CTS	Wt [lb]	Quantity	Part No	DG
3/8	1/4		10	93515	6
1/2	1/4	0.290	10	93511	6



**NEW**

**Viega PEX Press Ball valve**  
**Zero Lead**  
 - Brass  
 - Press connection  
 - Full port  
**Model 2842.2ZL**

P1	P2	Wt [lb]	Quantity	Part No	DG
3/8	3/8	0.280	10	94500	6
1/2	1/2	0.299	10	94521	6
3/4	3/4	0.395	10	94541	6



**NEW**

**Viega ProPress Valve**  
**Zero Lead**  
 - For copper manifolds  
 - Brass  
 - Press connection, male copper tube size  
Note  
 1/2" ProPress tool may be required  
**Model 2842.1ZL**

P	FTG	Wt [lb]	Quantity	Part No	DG
1/2	1/2		10	95002	6