## WARNING

DUE TO THE FAST SWITCHING OF THE COMPONENTS IN THIS CONTROLLER/INVERTER PCB, EXCESSIVE HEAT IS GENERATED. WHEN REPLACING THE PCB IT IS NECESSARY TO APPLY THE GREASE BETWEEN THE IPM IC, DIODE BRIDGE AND HEAT SINK AND FASTEN TO THE HEAT SINK WITH THE ORIGINAL OR ENCLOSED SCREWS

FAILURE TO USE THE GREASE AND FASTEN THE PCB WITH ORIGINAL SCREWS WILL VOID THE WARRANTY. IF GREASE OR SCREWS ARE NOT INCLUDED WITH THIS PART "DO NOT INSTALL" PLEASE CONTACT YOUR PART PROVIDER IMMEDIATELY.

## Included in this KIT C:

 $K0700095054\ M3\ L14-4\ pcs$  .  $K000036795\ Heat\ Sink\ Grease\ 1pc.$ 

## Applies to these parts

K9707706178K9707039337K9707427332K9707039139K9707039146K9707039085K9707706567K9707039320K9707427325

## For Models

AOU12RLAOU12RLSAOU18RLQAOU9RLSAOU15RLQAOU12RLQAOU18CLAOU9RLQAOU18RLAOU9RLAOU9RL

