



SET184 Thermostat

(Replaces Whirlpool 279769 & Gem ET184)

Kit consists of:

- 1 - Thermal cut off 352F
- 1 - Hi - limit thermostat L248-80
- 1 - Instruction Sheet

WARNING

Disconnect all electrical power before servicing appliance.

Both thermostats must be replaced together.

Make the following checks when replacing the thermostat kit.

1. Damaged elements: Inspect and take continuity check across terminals.
2. Check for plugged lint screen.
3. Block vent: Flapper on vent may not open up to allow heat escape.
4. Bad blower wheel.
5. Check ground to coil.

To prevent early failure when replacing this kit, check and replace the cycling thermostat(s).

Sealed Unit Parts Co., Inc.

2230 Landmark Place • Allenwood, NJ 08720 USA
(732)223-6644 • Fax: (732)223-1617

www.supco.com

P/N 16716
Rev. 04062011



SET184 Thermostat

(Replaces Whirlpool 279769 & Gem ET184)

Kit consists of:

- 1 - Thermal cut off 352F
- 1 - Hi - limit thermostat L248-80
- 1 - Instruction Sheet

WARNING

Disconnect all electrical power before servicing appliance.

Both thermostats must be replaced together.

Make the following checks when replacing the thermostat kit.

1. Damaged elements: Inspect and take continuity check across terminals.
2. Check for plugged lint screen.
3. Block vent: Flapper on vent may not open up to allow heat escape.
4. Bad blower wheel.
5. Check ground to coil.

To prevent early failure when replacing this kit, check and replace the cycling thermostat(s).

Sealed Unit Parts Co., Inc.

2230 Landmark Place • Allenwood, NJ 08720 USA
(732)223-6644 • Fax: (732)223-1617

www.supco.com

P/N 16716
Rev. 04062011



SET184 Thermostat

(Replaces Whirlpool 279769 & Gem ET184)

Kit consists of:

- 1 - Thermal cut off 352F
- 1 - Hi - limit thermostat L248-80
- 1 - Instruction Sheet

WARNING

Disconnect all electrical power before servicing appliance.

Both thermostats must be replaced together.

Make the following checks when replacing the thermostat kit.

1. Damaged elements: Inspect and take continuity check across terminals.
2. Check for plugged lint screen.
3. Block vent: Flapper on vent may not open up to allow heat escape.
4. Bad blower wheel.
5. Check ground to coil.

To prevent early failure when replacing this kit, check and replace the cycling thermostat(s).

Sealed Unit Parts Co., Inc.

2230 Landmark Place • Allenwood, NJ 08720 USA
(732)223-6644 • Fax: (732)223-1617

www.supco.com

P/N 16716
Rev. 04062011



SET184 Thermostat

(Replaces Whirlpool 279769 & Gem ET184)

Kit consists of:

- 1 - Thermal cut off 352F
- 1 - Hi - limit thermostat L248-80
- 1 - Instruction Sheet

WARNING

Disconnect all electrical power before servicing appliance.

Both thermostats must be replaced together.

Make the following checks when replacing the thermostat kit.

1. Damaged elements: Inspect and take continuity check across terminals.
2. Check for plugged lint screen.
3. Block vent: Flapper on vent may not open up to allow heat escape.
4. Bad blower wheel.
5. Check ground to coil.

To prevent early failure when replacing this kit, check and replace the cycling thermostat(s).

Sealed Unit Parts Co., Inc.

2230 Landmark Place • Allenwood, NJ 08720 USA
(732)223-6644 • Fax: (732)223-1617

www.supco.com

P/N 16716
Rev. 04062011