


Tork Coreless High Capacity Bath Tissue Dispenser

Elevation
Design

Distributeur de Papier Hygienique
Grande Capacite Sans Centre Rigide


Dispensador del Papel Tisu Para
Bario de Alta Capacidad Sin Nucleo




www.torkusa.com




Tork Coreless High Capacity Bath Tissue Dispenser




1




2




3




4




5




6




7




8



9



Tork Coreless High Capacity Bath Tissue Dispenser



☐ **Disposal**

- **Damaged or malfunctioning product should be disposed of immediately to avoid potential of injury**
- **Products should be disposed of in accordance with applicable regulations**

☐ **Elimination:**

- **Les produits endommagés ou défectueux doivent être immédiatement jetés afin d'éviter tout risque de blessure**
- **Les produits jetés doivent être éliminés conformément aux réglementations en vigueur**

e **Eliminación:**

- **Los productos dañados o con mal funcionamiento deben desecharse inmediatamente para evitar posibles lesiones**
- **Los productos deben desecharse de acuerdo con las regulaciones aplicables**

☐ **Cleaning instructions**

- **Clean dispenser with mild detergent and soft cloth**

☐ **Instructions de nettoyage**

- **Nettoyez le distributeur avec un détergent doux et un chiffon propre**


e **Instrucciones de limpieza**

- **Limpe el dispensador con un detergente y un paño suave**

European Community Design Registration RCD 000929971



Manufactured for
Essity Professional Hygiene
North America LLC
Philadelphia, PA 19104
www.torkusa.com
Made in Poland



Manufactured for
Essity Professional Hygiene
North America LLC
Philadelphia, PA 19104
www.torkusa.com
Made in Poland