## INSTALLATION PROCEDURE FORDFLEX REPAIR CLAMP STYLES F1, F2 AND LARGER

The successful application of a repair clamp rests heavily on the installer. We suggest the following guidelines be adopted as routine practice.

CHECK THE DIAMETER OF THE PIPE TO MAKE CERTAIN YOU ARE USING THE CORRECT SIZE CLAMP

## **PREPARATIONS:**

- 1. Scrape the pipe to remove as much dirt and corrosion as possible so the surface is smooth.
- 2. Make certain the gasket is free of foreign matter and that nothing becomes lodged between the gasket and the pipe. Lubricate the pipe and/or gasket with soapy water or any other acceptable lubricant to achieve maximum results.
- 3. Use proper tools, avoid loose fitting wrenches and wrenches too short to achieve the proper torque of the nuts. A torque wrench is recommended.



Back off nuts to end of bolts, but DO NOT remove them. Separate clamp and position on the pipe with the bolt lug section on top.

**PRECAUTIONS:** 



Hook the middle bolt into the receiver lug and tighten the nut until the bolt is secure.

1. Repair clamps are not designed for pipe restraint. Make sure proper restraint is applied when required. 2. ALWAYS RECHECK TORQUE AND PRESSURE TEST FOR LEAKS BEFORE BACKFILLING. 3. Backfill and compact carefully around the clamp according to the pipe manufacturer's instructions.



ROTATE THE CLAMP in the direction of the arrow approximately 1/4 turn to ensure correct gasket positioning.

The (Q) assures you that the Ford

highest standard of excellence.

Repair Clamp is manufactured to the



Squeeze the two lug sections together. Tighten the bolts evenly with incremental torque settings, up to the recommended torque.

RECOMMENDED TORQUE		
Clamp Top Range	Bolt Diameter	Approx. Torque
Thru 5.62"	5/8"	30 / 35 ft. lbs.
6.35" & Above	5/8"	75 ft. lbs.

4. Tighten all sections of a multi-section clamp evenly and equally to the recommended torque. The Ford Meter Box Co., Inc. 775 Manchester Avenue, P.O. Box 443, Wabash, Indiana, USA 46992-0443

Telephone: 260-563-3171 FAX: 800-826-3487 Overseas FAX: 260-563-0167 http://www.fordmeterbox.com

FORM # 91702-99

04/04



**Quality Circle** 




Wrap Clamp Snap Clamp Economical Water Full Wrap Gasket Pipe Repair



FS1 All Stainless Steel



F1 **Removable Ductile** Iron Lugs



FIBC Repair of Integral **Bell Solvent PVC** 



FCC Repair of Solvent Weld PVC Coupling



The Ford Meter Box Co., Inc. 775 Manchester Avenue, P.O. Box 443, Wabash, Indiana, USA 46992-0443 Telephone: 260-563-3171 FAX: 800-826-3487 Overseas FAX: 260-563-0167 http://www.fordmeterbox.com