



A → B → C

1. Carefully unpack and identify all parts referring to illustration for parts identification.
2. Turn the power to the installation point OFF.
3. Install proper bulbs to the sockets referring to the marking and/or labels on the fixture for maximum wattage.
4. Insert glass (A) through iron ring (B) into base (C).
5. Restore power to the installation point and retain this sheet for future reference.