

McALPINE
Mountain PLUMBING PRODUCTS

-
- Technical drawing of a clean out assembly. The side view shows a vertical pipe with a diameter of $\varnothing 2"$ and a height of $4 \frac{3}{4}"$. A horizontal pipe, labeled $\varnothing 1 \frac{1}{4}"$ BRASS WALL PIPE, is connected to the side of the vertical pipe. The horizontal pipe is $12"$ LONG. A drain, labeled DRAIN 17GA, is located on the horizontal pipe. The distance from the vertical pipe to the drain is $1 \frac{3}{4}"$. The distance from the drain to the end of the horizontal pipe is $3 \frac{1}{4}"$. The end view shows a circular cap with a diameter of $\varnothing 2 \frac{3}{4}"$. The cap is secured with a bolt and nut, with a distance of $\frac{5}{8}"$ from the end of the horizontal pipe to the center of the bolt. A star symbol (*) is located on the side of the vertical pipe, indicating the location of the clean out cap. The label CLEAN OUT CAP points to the star symbol.

ONE YEAR WARRANTY ON PLATED FINISHES, 90 DAY WARRANTY ON ORB, EB, MHB, TB AND WCP AND LIFETIME ON PVD PROVIDED PROPER CARE HAS BEEN USED. ONE YEAR WARRANTY ON ALL PARTS. APPLIES TO ORIGINAL PURCHASER . CLAIMS REQUIRE PROOF OF PURCHASE

Form MT2000-2 Inst Sht